

Serial No. 10/734,214  
In re Office Action dated February 10, 2006  
Amendment dated May 10, 2006

**AMENDMENTS TO THE SPECIFICATION:**

Please replace paragraph [0029] of the specification with the following amended paragraph:

[0029] As can be best seen from Fig. 2, the bottom plate 6, in a region that in terms of the longitudinal direction of the bearing block 4 is located between the pivot axis 20 and the bearing block stops 30 (**shown in Fig.1**), there is a holder for the restoring spring elements 10, which is preferably embodied as a peg 42. The restoring spring elements, embodied for instance as helical springs inserted one inside the other, are slipped onto the peg 42 and centered on it. The bearing block 4 is preferably embodied as a one-piece plastic injection-molded part; that is, all the elements described thus far, such as the bottom plate 6, end plate 16, cheeks 14, crossbar 12, and in particular the bearing block stops 30, together form one integral component.